BUILDING SAFETY CERTIFICATE

No.	~	07	0
140.	_	٥7	بر

Dated: 14-06-24

Certified that the existing building SANSKAR PUBLIC SChool (name of the
Building or premises) at NASIUGE & POST WALLDAON TEHSIL GIWALIOR
LAROYAD FLOOR + FIRST FLOOR TOTAL ARFA 2850.55 SG MIR
(upper floors) owned/occupied by SANSKAR PUBLIC SCHOOL ISWALLOR MP
(name of the Institution) have complied with the Building safety requirements in accordance with
National Building code Rules, and verified by the officers concerned of
DEPART MENT (Name of Department / Govt.) on .06-06-2024
(date of inspection) in the presence of SHRI KRISHAN GUPTA PANT NA WAR U
(name and addresses of the Manager/Secretary or his representative) and that the building/premises is
fit for occupancy upto classesX.J.J.Th (X / XII) with effect fromOMEY PROMET For a period of
ك.م.ك.ك Years in accordance with rule and subject to compliance of the specific conditions as
Appended.
1 - 10 - 20
1. SAFE DRINKING WATER
2. SANITARY
3. FIRE SEFETY
4.
Issued on 14-06-24 at Gwallon S. L by
* Strike out whichever is not applicable. Executive Engineer
PWD Dn.No.1, Gwalior
Signature with Seal :
1/20497
Assistant Engineer Name: OM HARS SHARMA
P.W.D. Doad Sub Division Designation:
Gwahor (M.R.)
Name & Address of Department/Office :

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only.

(Assistant Engineer & Above officer of concerned Govt. Department only)

कार्यालय कार्यपालन यंत्री, लोक निर्माण विभाग संभाग क्र. 1, ग्वालियर

web site : www.mp.gov.in/pwdmp

E-Mail: eepwd1gwl@mp.nic.in

Phone No. 0751-2371231

दिनांक 1416124

प्रति,

संयुक्त संचालक लोक शिक्षण संभाग ग्वालियर (म.प्र.)

विषय :- भवन सुरक्षा प्रमाण-पत्र जारी करने के संबंध में।

संदर्भ :— आपका कार्यालयीन पत्र कं. मान्यता / भ.सु.प्र.प्र. / 2024—25 / 1939 ग्वालियर दिनांक 16.05.2024

उपरोक्त विषयांतर्गत संदर्भित पत्र के तारतम्य में अनुरोध कर लेख है कि अशासकीय संस्कार पब्लिक स्कूल ग्वालियर ग्राम व पोस्ट नौगॉव जिला ग्वालियर स्थित विद्यालय भवन का अनुविभागीय अधिकारी लोक निर्माण विभाग रोड उपसंभाग ग्वालियर एवं संबंधित उपयंत्री द्वारा निरीक्षण कराया गया, उनके द्वारा प्रस्तुत विद्यालय भवन का सुरक्षा प्रमाण–पत्र आपकी ओर आवश्यक कार्यवाही हेतु संलग्न प्रेषित है। सहपत्र :— उपरोक्तानुसार।

कार्यपालन यंत्री लोक निर्माण विभाग संभाग क्र. 1 भी